

FIG. 1 (RELATED ART)




FIG. 2 (RELATED ART)

+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+

FIG. 3a (RELATED ART)

-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-
-	+	-	+	-	+	-	+
+	-	+	-	+	-	+	-

FIG. 3b (RELATED ART)

0611-9878-USf/yvonne/touko




FIG. 4 (RELATED ART)




FIG. 5a (RELATED ART)




FIG. 5b (RELATED ART)

0611-9878-USf/yvonne/touko




FIG. 6

0611-9878-USf/yvonne/touko

600	+	-	+	-	+	-	+	-
604	+	-	+	-	+	-	+	-
601	+	-	+	-	+	-	+	-
605	+	-	+	-	+	-	+	-
602	-	+	-	+	-	+	-	+
606	-	+	-	+	-	+	-	+
603	-	+	-	+	-	+	-	+
607	-	+	-	+	-	+	-	+
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	-	+	-	+	-	+	-	+
	-	+	-	+	-	+	-	+

FIG. 7a

600	-	+	-	+	-	+	-	+
604	-	+	-	+	-	+	-	+
601	-	+	-	+	-	+	-	+
605	-	+	-	+	-	+	-	+
602	+	-	+	-	+	-	+	-
606	+	-	+	-	+	-	+	-
603	+	-	+	-	+	-	+	-
607	+	-	+	-	+	-	+	-
	-	+	-	+	-	+	-	+
	-	+	-	+	-	+	-	+
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-

FIG. 7b

600	+	-	+	-	+	-	+	-
604	+	-	+	-	+	-	+	-
601	+	-	+	-	+	-	+	-
605	+	-	+	-	+	-	+	-
602	+	-	+	-	+	-	+	-
606	+	-	+	-	+	-	+	-
603	+	-	+	-	+	-	+	-
607	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-

FIG. 8a

600	+	-	+	-	+	-	+	-
604	+	-	+	-	+	-	+	-
601	+	-	+	-	+	-	+	-
605	+	-	+	-	+	-	+	-
602	+	-	+	-	+	-	+	-
606	+	-	+	-	+	-	+	-
603	+	-	+	-	+	-	+	-
607	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-
	+	-	+	-	+	-	+	-

FIG. 8b